Work Order ID 58189



Page 1

Tuesday, April 27, 2010 4:07:06 PM

Item ID:

D4020-1

Accept



Setup Start

Štop



Revision 1D:

Item Name: Start Date:

4/27/2010

Mesh (350 Basket Long, Base)

Start Otv: 1.00

Rea'd Otv: 1.00



Cust Item ID:

Customer:

Reference:

Approvals:

Sequence ID/

Process Plan: MF

Date: (0-4-27 Tooling:

Date:

Start Run



OC:

Date: _____

SPC (Y/N):

Date:

Accept

Reject

Stop

Insp. Stamp

Work Center ID Draw Nbr

Operation Description

Revision Nbr

Set Up/ Run Hours

Draw Number

Draw Rev.

Plan Code Qty

Otv

Reject Number

D4020 Α

Required Date: 4/28/2010

100

Shear

Shear

FLOW WATER JET

Memo

1-Cut to lenght 95.25" as per Dwg D4020

0.00

0.00

10-04-27

120

Quality Control

OC5- Inspect part completeness to step on W/O

0.00

Memo

0.00

10,04,23

130

Packaging Packaging

Identify as per dwg & Stock Location:

0.00

0.00

SY 10/04/28 1

W/O:	erospace Lt		\\/	ODK ODDED CHAN	ICEC .						
DATE	STEP	PROCEDURE CHANGE				Ву	,	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspect
							!	:			
		: 						i			
Part No	·	DAD #:	Fault Oat			-	.1				
				egory:							
		lution:									
NCR:		lution:	Disposition		QA: I	₩C	Clos	ed:			
NCR:	Reso	lution:	Disposition	on:OER NON-CONFORM	QA: I	₩C	Clos	sed:		Date:	
		lution:	Disposition	on:OER NON-CONFORM	QA: I	₩C	Clos CR)	ed:	ation		Approva
NCR:	Reso	lution: Description of NC	WORK ORD	DER NON-CONFORM Corrective Action Security Action Description	QA: I	V/C (NC Sigr	Clos CR)	ed:	ation	Date:	Approva
NCR:	Reso	lution: Description of NC	WORK ORD	DER NON-CONFORM Corrective Action Security Action Description	QA: I	V/C (NC Sigr	Clos CR)	ed:	ation	Date:	Approva
NCR:	Reso	lution: Description of NC	WORK ORD	DER NON-CONFORM Corrective Action Security Action Description	QA: I	V/C (NC Sigr	Clos CR)	ed:	ation	Date:	
NCR:	Reso	lution: Description of NC	WORK ORD	DER NON-CONFORM Corrective Action Security Action Description	QA: I	V/C (NC Sigr	Clos CR)	ed:	ation	Date:	Approva

NOTE: Date & initial all entries

Work Order ID 58189

Page 2

Tuesday, April 27, 2010 4:07:06 PM

Item ID:

D4020-1

Accept

Setup Start

Stop



Revision ID:

Start Date:

Item Name:

Required Date: 4/28/2010

4/27/2010

Start Qty: 1.00

Req'd Qty: 1.00

Operation

Description

Cust Item ID:

Customer:

Reference:

Approvals:

QC:

Process Plan:

Mesh (350 Basket Long, Base)

QC21- Final Inspection - Work Order Release

Date:

Tooling:

SPC (Y/N):

Set Up/

Run Hours

Date:

Date:

Run Start



Stop

Sequence ID/

Work Center ID

140

Memo

Date: ____

0.00

0.00

Draw Number

Draw Rev.

Accept Plan Code Qty

Reject Qty

Reject Insp. Number

Stamp

Quality Control

	•					:				1	
Dart Ae W/O:	rospace	e Ltd		1001/ 00000						·	
DATE	STEP	WORK ORDER CHANGES PROCEDURE CHANGE					Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspect	
							ï				
,											
Part No		PAR #:									
	R	esolution:	Disposit	Disposition: QA:			VC Closed: Date:				
NCR:			WORK ORI	DER NON-CONFORMAN	ICE (N	ICR)	:				
D		Description of NC	Corrective Action Section B				Vorific	ation		Approva	
DATE	STEP Description of No		Initial Chief Eng	Action Description Chief Eng		gn & late	Section		Approval Chief Eng	Approva QC Inspect	
			1,10					- "	<u> </u>		

NOTE: Date & initial all entries

Picklist Print

Tuesday, April 27, 2010 4:07:06 PM

Work Order ID: 58189

Parent Item:

D4020-1

Parent Item Name:

Mesh (350 Basket Long, Base)

Comments:

IPP RevA: new issue DD 09.11.26 verified by:EC

per dwg revA 10.03.15 verified by:EC



IPP Rev:B as

Start Date: 4/27/2010

Required Date: 4/28/2010

Start Oty: 1.00

Required Oty: 1.00

Component Item ID/ Item Name

Replacement Mfg/ Item ID Purch

Purchased

Bin Primary Item Location No

Last Location Route Seq ID 100

Unit of Oty on Measure sf

Hand 578,5985 34,2895

Remaining Otv Qty To Pick Issued Date Issued Status

Page 1

M304EX0.75-16F

Expanded Metal Flat SS

SAD 10-04-27


Warehouse Loc Qty Loc Code Location Main Warehouse MAT 578.5985368 111956 28 112949 12 113497 6.34 113555 258.163684 114212 12.1241526 114399 261.9707

				•				•	
Dart Ae	rospace	e Ltd	İ					,	T
₩/o: →				WORK ORDER (CHANGES		· · · · · · · · · · · · · · · · · · ·	*	
DATE	STEP		PROCEDUR	E CHANGE		Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspect
					₂₄ . b				
Part No		PAF		It Category:		i			J
NCR:). f	WORK	ORDER NON-CON		I			
DATE	STEP	Description of Section A	NC Init	Corrective Action Action Description Eng Chief Er	cription	Sign &	Verification Section C	Approval Chief Eng	Approva QC Inspecto
As To you		.~							
								· · ·	

180° 180°

NOTE: Date & initial all entries

H:\fFORMS\Quality Assurance\approved QA\NCRWO RevE



Dart Ae	rospace	e Ltd					-					مر e رکافیه
W/O:				WC	ORK ORDER C	HANGES						
DATE	STEP	P	PROCEDURE CHANGE				Ву	Date		Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
Part No):	PAR #:		Fault Cate	gory:	NC	R. Ve	e N	o DOA		Date	
	R	esolution:		_ Disposition	n:	Q <i>A</i>	: N/C	Clos	ed:	\•	_ Date: _	
NCR:					ER NON-CONF							
DATE		Description of NC		Corrective Action Section B				***************************************	Verific		Ammuoval	Annrova
DATE	STEP	Section A		Initial Chief Eng	Action Descr Chief Eng	iption	Sig	n & ite	Section		Approval Chief Eng	Approva QC Inspecto
}		198							•			
	,					7			•		1.51	
									1			
							A CONTRACTOR OF THE CONTRACTOR					
						•						
		,						-	:			
					•							

NOTE: Date & initial all entries